

Consew CM-101-1: Drilling Tabletop Holes to Install the Motor and Machine Head

See pictures below. The first series are for the motor (pictures are taken facing the bottom of the table top). The next series are for the base of the machine (pictures are taken facing the top of the table top). It's very important to make sure the puller for the motor and the handwheel on the machine are mounted so that the belt is in the center of the slot. There may be some variability in measurements to get the pulley and handwheel exactly in the center of the slot.













































